

IMPORTANT INFORMATION

INFLATABLE LIFEJACKETS

Date: 01/11/2019

Products concerned:

All Baltic inflatable lifejackets

All Baltic inflatable lifejackets in the Industrial range made from 01/02/2013 and all other Baltic inflatable lifejackets from 01/09/2013 are equipped with a cylinder retainer (see pictures) to ensure that the CO₂ cylinder cannot be released. Also check that the cylinder retainer o-ring is intact, if necessary it should be replaced with a new one provided free of charge by Baltic. As per our service instructions, all our inflatable lifejackets should be serviced once a year or alternatively a self-check can be performed according to our instructions, see: www.baltic.se. If the annual service/inspection has not been done since 2013, please contact one of our service stations or alternatively us at Baltic to service the lifejacket and if necessary have a retainer mounted free of charge. Our customer service can be reached at +46 506-36990 , +44 2380457272 (UK) or info@baltic.se, sales@baltic-uk.com (UK)

